



LEOPARD FAMILY

# *||EXMATE* BL-40H

Leopard Temperature Meter 4 Digit 0.56" LEDs in a 1/16 DIN CASE

# An economically smart temperature meter relay for J, K, R, and T type thermocouple and RTD inputs.

#### **General Features**

CE

- Thermocouple (J, K, R and T types) or RTD (Pt-100. 385 and 392 curves. 3 wire/4wire). Digitally Linearized.
- Optional isolated 16 bit analog output. User or factory scalable to 4 to 20 mA, 0 to 20 mA or 0 to 10 V across any desired digital span from ± one count to the full scale range of – 1999 to 9999 (12000 counts).
- Auto-sensing AC/DC power supply. For voltages between
   85-265 V AC / 95-370 V DC (PS1) or 15-48 V AC / 10-72 V DC (PS2).
- Standard red or optional green or super bright red 4-digit LED
- Three annunciator LEDs provide front panel alarm status indication for up to three setpoints.
- One 10 Amp Form C and one 5 Amp Form A relay, or up to three 5 Amp Form A relays are available.
- When analog output is installed, one 10 Amp Form C or two 5 Amp Form A relays can be supported.

#### Software Features

- Three-button programming from the front panel (UP, DOWN and PROGRAM buttons).
- Three front panel selectable ranges.
- Front panel selectable four-level brightness control of digital display, and setpoint LEDs.
- Three programmable setpoints.

Calibration Procedure ......4

Case Dimensions......10

Component Layout .....9

Connector Pinouts .....7

- Relay activation can be selected to occur above (HI) or below (LO) each setpoint.
- Hysteresis setting for all three setpoints. Delay on make and delay on break for SP1 and SP2.

### Input Module Compatibility

There are 2 different Plug-in Modular Input Signal Conditioners for this specialized temperature only member of the Leopard Family. IT10 is for J, K, T and R thermocouples. IT11 is for 3 wire/4 wire Pt-100 RTD inputs.




LEOPARD

## **Specifications**

Input Specs:	Depends on input signal conditioner			
A/D Converter:	14 bit single slope			
Accuracy:	$\dots \pm (0.05\%$ of reading + 2 counts)			
Temp. Coeff .:	100 ppm/°C (Typical)			
Warm up time:				
Conversion Rate:	5 conversions per second (Typical)			
	4 digit 0.56" Red LED display (std),			
	0.56" Red, Green or Super Bright Red			
	(optn). Range –1999 to 9999 counts.			
Polarity <sup>.</sup>	Assumed positive. Displays – negative			
•	Automatic by resolution select XXX•X			
	Top segments of digital display flash			
<b>Negative Overrange</b> Bottom segments of digital display flash				
• •	Three 5 Amp Form A relays or one 10 Amp			
	Form C, and one 5 Amp Form A relay.			
	Isolated 16 bit user scalable mA or V			
· · · · ·				
, ,	. 0-10 V DC @ 500 $\Omega$ or higher resistance			
	AC/DC Auto sensing wide range supply			
	85-265 VAC / 95-370 VDC @ 2.5W max 3.2W			
	15-48 VAC / 10-72 VDC @ 2.5W max 3.2W			
Operating Temp.:0 to 60 °C				
Storage Temp:	–20 °C to 70 °C.			
Relative Humidity:95% (non condensing)				
Case Dimensions:1/16 DIN, Bezel: 96x24mm (3.78"x0.95")				
	Depth behind bezel 122.2 mm (4.83")			
	Plus 12.7mm (0.5") for Right-angled			
	connector.			
Weight:	7 oz., 9 oz when packed			

Weight:.....7 oz., 9 oz when packed

#### Index



# Front Panel Buttons

## Program Button

The P button is used to move from one program step to the next. When pressed at the same time as the P button, it initiates the **calibration mode**. When pressed at the same time as the P button, it initiates the **setpoint setting mode**.

## Up Button

When in the operational display, pressing the 1 button alone allows you to view, but not change, the setting of **setpoint 1**.

When in the **calibration mode** or the **setpoint setting mode** the button is used to increase the value of the displayed parameter.

#### Down Button

When in the operational display, pressing the 🖲 button alone allows you to view, but not change, the setting of **setpoint 2**.

When in the **calibration mode** or the **setpoint setting mode** the button is used to decrease the value of the displayed parameter.

## **Glossary of Programming Symbols**


To explain software programming procedures, logic diagrams are used to visually assist in following the programming steps. The fol-lowing symbols are used throughout the logic diagrams to represent the buttons and indicators on the meter:




the

When two displays are shown together with bursts, this indicates that the display is toggling (flashing) between the name of the function and the value.


[Span] [10000] Text or numbers shown between square brackets in a procedure indicate the programming code name of the function or the value displayed on the meter display.



When the 🖈 and 🖲 buttons are shown together, the display value can be increased by pressing and releasing the 🗈 button or decreased by pressing and releasing the 🖲 button.



When the 
and 
buttons are shown with two displays, either display can be selected by pressing and releasing the 
or buttons.





When there are more than two display selections they are shown in brackets below the first display and are also selectable by pressing and releasing the for subttons.

A dotted box indicates these functions are omitted or bypassed when the related hardware is not present



Symbol

#### Explanation

This symbol represents OPERATIONAL DISPLAY.



₽

This is the PROGRAM button.

This is the UP button.

This is the DOWN button.



When a button is shown, press and release it to go onto the next step in the direction indicated by the arrow. When two or more buttons are shown, each with an arrow, this indicates that there is a number of programming choices.



When two buttons are shown side by side and enclosed by a dotted line, they must be pressed at the same time then released to go onto the next programming step.




If the display is shown with XXXX it means the value displayed will be the previously set value. When a number is shown it indicates the initial factory default setting or a specific "example number".

## Software Logic Tree

The BL-40H is an intelligent meter with a hierarchical software structure designed for easy programming and operation, as shown below in the software logic tree.

MAIN MENU Operational Display After the meter has been powered up, the four digits light up for three seconds and then settle to the operational display indicating the input signal.



in the preceding step will not be saved.

°F \_\_\_\_\_

F

## Thermocouple or RTD Sensor Type Selection

- STEP A Enter the Sensor Type Selection Mode Through the Sub Menu [CAL] [oFF] 1) Press the P and the buttons at the same time.
  - Display toggles between [CAL] and [oFF].
  - 2) Press the P button. Display toggles between [Br] and the previous [Br] setting
  - 3) Press the P button. Display toggles between [AnLo] and the previous [AnLo] setting (if analog output option is installed).
  - 4) Press the P button and depending on the module installed the display will either toggle between [thEr] and the thermocouple selected [J], [K], [R] or [T] or [RTD] and the RTD type selection [P385] or [P392].

## STEP B Sensor Type Selection

- 1) Using the 1 and 1 buttons, adjust the display to the desired sensor type
- 2) Press the D button. Display toggles between [rES] resolution select and previous [rES] setting.

## STEP C Set the Resolution

- 1) Using the 🗈 and 🖳 buttons, adjust the display to the desired resolution [rES] value.
- 2) Press the P button. Display toggles between [dEG] and previous [dEG] selection.

## STEP D Selection of Degree C or Degree F

- Using the ▲ and ▲ buttons, adjust the display to either °C or °F.
   Press the ▶ button. The meter exits the sensor type selection
- mode and returns to the operational display.


# **Calibration Procedure**


## IT10 Thermocouple Input Signal Conditioner installed.


- Unplug the connector plugs from the meter. Remove the 1. case back panel and slide the PCB out of the case.
- 2. Select the appropriate header jumper position depending on which thermocouple is to be used. Thermocouple types J, K, R and T are supported. This sets up the correct cold junction compensation.
- 3. Insert the PCB back into the case. Snap the back panel back into the case. Apply power to the meter.
- 4. Enter the program mode and select the type of thermocouple (J, K, R, T), the resolution (0.1° or 1°) and the display units .°C or °F). See the Software Logic Tree on Page 3 of the data sheet for details.
- 5. Connect a thermocouple simulator to the meter inputs. Apply an input corresponding to 0° and adjust the ZERO Potentiometer to make the display read 0.
- 6. Apply an input corresponding to the maximum reading of the thermocouple and adjust the SPAN Potentiometer to make the display read correctly.
- 7. The DL-40H is now calibrated and ready for use. Calibration will have to be performed again if the thermocouple type is changed.


## IT11 RTD Input Signal Conditioner installed.


- 1. Enter the program mode and select the type of RTD (385 or 392 curve and 3-wire/ 4-wire), the resolution (0.1° or 1°) and the display units ·°C or °F). See the Software Logic Tree on Page 3 of the data sheet for details.
- 2. Connect an RTD simulator to the meter inputs. Apply an input corresponding to 0° and adjust the ZERO Potentiometer to make the display read 0.
- 3. Introduce a lead resistance of  $10\Omega$  in each lead. Adjust the Lead Resistance Compensation potentiometer to make the display again reads 0.
- The DL-40H is now calibrated and ready for use. Calibration will have to be performed again if the RTD type is changed.











Symbols Indicate Module Compatibility Within Meter Families

### **Two Point Analog Output Range Setting and Calibration**

#### STEP A Enter the Calibration\_Mode

- Press the P and ▲ buttons at the same time. Display toggles between [cAL] and [oFF] if the Analog Output option is installed. If at this point the display skips directly to toggle between [Br] and the previous [Br] setting (STEP D) then the software is detecting that the optional analog output hardware is NOT installed.
- 2) Press the or button. Display changes from [oFF] to [on].

#### STEP B Enter the Analog [oUT] Output Mode

1) Press the D button. Display toggles between [cLo] and an internal scale factor.

#### STEP C Set or Calibrate the [cLo] Low Analog Output Range

- 1) Select the voltage or current loop output header position on the output module. (See Component Layout on page 9).
- 2) Connect a multimeter to pins 8 and 9 on the output module. (See Rear Panel Pinouts on page 8). Using the <sup>●</sup> and <sup>●</sup> buttons, adjust the analog output to the desired low value as shown on the multimeter display. cLo may be adjusted to any value from -0.3 mA to 17 mA (mA output selected) or from -0.6 V to 8 V (volt output selected)
- 3) Press the P button. Display toggles between [chi] and an internal scale factor.

#### STEP D Set or Calibrate the [chi] High Analog Output Range

- Using the and buttons, adjust the analog output to the desired high value as shown on the multimeter display. chi may be adjusted to any value from 17 mA to 21 mA (mA output selected) or from 8 V to 10.3 V (volt output selected)
- 2) Press the P button. The display exits the calibration mode and returns to the operational display.

**Note**: Having established the Low and High range of the analog output, the digital span can now be selected which will set the two digital points between which the analog output will occur. (See Digital Span Selection below).

#### **Brightness Selection**

#### STEP D Enter the Brightness Mode Through the Sub Menu [cAL] [oFF]

- 1) Press the 🖻 and 🗈 buttons at the same time.
  - Display toggles between [cAL] and [oFF].
- 2) Press the P button. Display toggles between [Br] and the previous [Br] setting.

#### STEP E Set the Display Brightness

- 1) Using the and buttons, adjust the display to the desired brightness setting (4 is the brightest setting).
- 2) Press the ₱ button. Display brightness changes to new setting and display toggles between [Anhi] and the previous [Anhi] setting.

## **Digital Span Selection for Analog Range Output**


#### STEP F Setting the Digital Span Point for Analog High Output

- Using the and buttons, adjust the display to the desired digital value which sets the point at which the selected analog high output range will occur.
   Press the button. Display toggles between [AnLo] and previous [AnLo] setting.
  - 2) Press the 🗀 button. Display toggles between [AnLo] and previous [AnLo] setting.

#### STEP G Setting the Digital Span Point for Analog Low Output

- 1) Using the and buttons, adjust the display to the desired digital value which sets the point at which the selected analog low output range will occur.
- 2) Press the P button. The display exits the calibration mode and returns to the operational display.

**Note**: Any two digital scale points from -1999 to 9999 can be selected. The digital scale points for analog high and analog low can be reversed for reversed 20-4 mA output. The span of the digital scale can be as small as two counts however small spans cause the 16 bit D to A to increment in stair case steps.



## Setpoint Setting and Relay Configuration Mode

The following programming steps are required to enter the setpoint values and configure the relay functions in a meter with four relays using four setpoints. Generally if less than four relays are installed the software auto detects missing relays and deletes reference to them from the menu. In some cases setpoints without relays are operational for display only purposes.

#### STEP A Enter the Setpoint Mode

Press the 
 P and 
 ■ buttons at the same time.
 Display toggles between [SP1] and the previous [SP1] setting.

#### STEP B Set Setpoint 1 (SP1)

- Using the and buttons, adjust the display to the desired SP1 value.

#### STEP C Set the Hysteresis Setting for Setpoint 1

- 1) Using the and buttons, adjust the display to the desired hysteresis [HYSt] value.
- 2) Press the P button. Display toggles between [SP2] and the previous [SP2] setting.

**NOTE**: Half of the Hysteresis value selected is applied above and below the setpoint.

#### STEP D Set Setpoint 2 (SP2)

- Using the and buttons, adjust the display to the desired SP2 value.

#### STEP E Set the Hysteresis Setting for Setpoint 2

- 1) Using the and buttons, adjust the display to the desired hysteresis [HYSt] value.
- 2) Press the <sup>₱</sup> button. Display toggles between [SP3] and the previous [SP3] setting.

#### STEP F Set Setpoint 3 (SP3)

- Using the and buttons, adjust the display to the desired SP3 value.
- 2) Press the <sup>P</sup> button. Display toggles between [HYSt] and the previous [HYSt] setting.

#### STEP G Set the Hysteresis Setting for Setpoint 3

- Using the and buttons, adjust the display to the desired hysteresis [HYSt] value.


#### STEP H Set Relay Activation mode [rLYS]

(H) High the relay energizes when the setpoint is exceeded. (L) Low the relay energizes below the setpoint. The setpoint is indicated from left to right SP1, SP2, SP3.


- Using the and buttons, adjust the reading on the display to the desired relay settings: [LLL-], [LHL-], [LLH-], [HHH-].
   If only 2 relays installed [LH] [HL] [HH] [LL].
- 2) Press the P button.

The meter exits the setpoint mode and returns to the operational display.

#### The Setpoint Relay programming mode is now complete.




#### **Functional Diagram**



#### **Connector Pinouts**

# **Rear Panel Pinout Diagram**


This meter uses plug-in type screw terminal connectors for all input and output connections.



### **Connectors**

The BL-40H uses plug-in type screw terminal connectors for all input and output connections. The power supply connections (pins 14 and 15) have a unique plug and socket outline to prevent cross connection. The main board uses standard right-angled connectors.

Replacement 2-, 3-, and 4-pin plug connectors are available (see Accessories on page 12).






WARNING: AC and DC input signals and power supply voltages can be hazardous. Do Not connect live wires to screw terminal plugs, and do not insert, remove or handle screw terminal plugs with live wires connected.

## *Pin Descriptions* Input Signal – Pins 1 to 6

Pins 1 to 6 are reserved for the input signal conditioner. See the data sheet for the selected input signal conditioner.

## Pins 8 to 12 - Relay and Analog Output Pins




## Pins 14 and 15 – AC/DC Power Input

Auto sensing AC/DC power supply. For voltages between 85-265 VAC or 95-370 VDC (PS1).

**Pin 14 & Pin 15** - AC/DC Power Input: These pins are the power pins of the meter and they only accept a special polarized screw terminal plug that can not be inserted into any other input socket. The standard meter has a auto sensing AC/DC power supply that operates from 85-265 VAC/95-370 VDC (PS1 Std). An optional isolated low voltage power supply that operates from 15-48 VAC/10-72 VDC (PS2) is also available.


# **Internal Header Pin out**




Internal header pins 1, 2, 3, 6, and 7 are for factory settings only. Not for external use!

**4 HOLD.** By connecting the HOLD pin to the GND pin, the displayed reading is frozen, however, A/D conversions continue. When the HOLD pin is disconnected from the GND pin, the correct reading is displayed.

5 GND. This pin is connected to the internal power supply ground.





## I-Series Input Signal Conditioning Modules

Symbols Indicate Module Compatibility Within Meter Families					
TIGER Family	TIGER Family	TIGER Family			
LEOPARD Family	LEOPARD Family	LEOPARD Family			
LYNX Family	LYNX Family	LYNX Family			
ALL MODELS	SOME MODELS	MODEL SPECIFIC			


Pre-calibrated **I-Series** input modules, that have span or zero potentiometers, can be interchanged between any **I-Series** compatible meter, without recalibration, because all of the analog scaling and reference circuitry is self-contained within the module.

Unless otherwise specified Texmate will ship all modules pre-calibrated with factory preselected ranges and/or scalings as shown in **BOLD** type. Other pre-calibrated standard ranges or custom ranges may be ordered. Factory installed custom scaling and other custom options are also available (see Ordering Information, Special Options on last page).




**WARNING:** AC and DC input signals and power supply voltages can be hazardous. Do Not insert, remove or handle modules with live wires connected to any terminal plugs.


IT10: Thermocouple, J/K/R/T, Selectable C/ F, 1 /0.1



**IT11**: RTD, 100Ω Pt. Select **3**/4-wire, °C/°**F, 1**°/0.1° **IT15**: RTD, 1000Ω Pt. Select 3/4-wire, °C/°**F, 1**°/0.1°




#### **Case Dimensions**







# Smart, Programmable Bargraph Relays with Isolated 16 Bit 4-20 mA or 0-10 V Outputs



BASIC MODEL # DISPL	AY POWER SUPPLY INPUT	MODULES ANALOG OUTP	UT RELAY OUTPUT OPTIONS / ACCESSORIES	
BL-40H -			OA	
indicate how ma	pasic model number the order code suffix ny different special options and or acces F10-0IC-R1-0A2, the 2 OA's are, CR-C	sories that you may require to	be included with this product.	
► BASIC MODEL NUMBER BL-40H96x24mm, Leopard, 4 [	Digit, Temperature	Special Option Part Number	s and Accessories (OA's)	
Standard Options for thi	s Model Number		IS (Specify Inputs or Autouts & Dog Deading)	
Order Code Suffix	Description	► SPECIAL OPTIONS (Specify Inputs or Outputs & Req. Reading) CR-CHANGE Calibrated Range Change to another Standard Range CS-L/40 Custom Scaling within any Stnd. or Custom Selectable Range		
►DISPLAY DR Red LED, 0.56 inch high DBSuper-bright Red LED, 0.56 inch high DGGreen LED, 0.56 inch high		CSR-L/40 Custom Selectable Range Installation or Modification CSS-L/40 Custom Special Scaling beyond the Standard Range COA-L/SINGLE Custom Output - Special Scaling of Analog Output COR-L/RELAY Custom Output - Relays Installed in Non-Standard Locations		
► POWER SUPPLY PS1 . 85 - 265VAC / 95 - 370VDC PS2 15 - 48VAC / 10 - 72VDC		CCP-L/SETUP NRC to Set-up Custom Configuration - Functions, Codes CCP-L/INSTL Factory Installation - Custom Configuration ACCESSORIES 75-DBBZ96X24 Black Bezel for 96x24mm Case 75-DMTC96X24 Side Slide Brackets (2 pc) - extra set, extra strength		
► INPUT MODULES (Partial List. See www.texmate.com) Unless otherwise specified Texmate will ship all modules precalibrated with factory preselected ranges and/or scalings as shown in <b>BOLD</b> type.		ART-FS-S/D/C NRC for artwork & set-up Faceplate/Desc/Co.Logo ART-FS-S/D NRC for artwork & set-up Faceplate/Desc ART-FS-001 Install Custom Faceplate per meter - 1 color 93-PLUG2P-DP Extra Screw Terminal Conn., 2 Pin Power Plug		
IT10Thermocouple, J/K/R/T, Selectab IT11RTD, 100 $\Omega$ Pt. Selectable 3/4-wi		93-PLUG2P-DR Extra Screw Terminal Conn., 2 Pin Plug 93-PLUG3P-DR Extra Screw Terminal Conn., 3 Pin Plug 93-PLUG4P-DR Extra Screw Terminal Conn. 4 Pin Plug		
►ANALOG OUTPUT* OICIsolated analog 4-20mA (with a Max. Two-5A Form A Relays) OIVIsolated analog 0-10VDC (with a Max. Two-5A Form A Relays) *Note: When either of the Analog Output options is installed, only the R1, R2 and R11 Relay Output options can be co-installed (see below).		<ul> <li>93-PLUG4P-DR Extra Screw Terminal Conn., 4 Pin Plug</li> <li>DN.CAS96X24L Complete 96x24mm Case with bezel</li> <li>OP-MCLP96X24 Screw Mounting Clips (2 pc) - to screw tighten slide brackets</li> <li>OP-MTLCLIP Screw Mounting Clips (2 pc) to screw tighten slide brackets</li> <li>75-DTP96X24 Black Metal Trim Plate (96x24mm Case) 1 Meter</li> <li>75-DTP2X9624 Black Metal Trim Plate (96x24mm Case) 2 Meters</li> <li>75-DTP3X9624 Black Metal Trim Plate (96x24mm Case) 3 Meters</li> </ul> Many other options and accessories are available. See full price list for more details. Prices subject to change without notice.		
<ul> <li>▶ RELAY OUTPUT</li> <li>R1 Single 5A Form A Relay</li> <li>R2 Dual 5A Form A Relays</li> <li>R3 Three 5A Form A Relays; SP1 &amp; SP2 common**</li> <li>R11 Single 10A Form C Relay</li> <li>R16 Single 10A Form C &amp; Single 5A Form A Relays**</li> <li>**R3 &amp; R16 cannot be co-installed with Analog Output options.</li> </ul>				
WARRANTY		USER'S RESPONSIBILI	тү	

Texmate warrants that its products are free from defects in material and workmanship under normal use and service for a period of one year from date of shipment. Texmate's obligations under this warranty are limited to replacement or repair, at its option, at its factory, of any of the products which shall, within the applicable period after shipment, be returned to Texmate's facility, transportation charges pre-paid, and which are, after examination, disclosed to the satisfaction of Texmate to be thus defective. The warranty shall not apply to any equipment which shall have been repaired or altered, except by Texmate, or which shall have been subjected to misuse, negligence, or accident. In no case shall Texmate's liability exceed the original pur-chase price. The aforementioned provisions do not extend the original warranty period of any product which has been either repaired or replaced by Texmate.



We are pleased to offer suggestions on the use of our various products either by way of printed matter or through direct contact with our sales/application engineering staff. However, since we have no control over the use of our products once they are shipped, NO WARRANTY WHETHER OF MERCHANTABILITY, FITNESS FOR PURPOSE, OR OTHERWISE is made beyond the repair, replacement, or refund of purchase price at the sole discretion of Texmate. Users shall determine the suitability of the product for the intended application before using, and the users assume all risk and liability whatsoever in connection therewith, regardless of any of our suggestions or statements as to application or construction. In no event shall Texmate's liability, in law or otherwise, be in excess of the purchase price of the product.

Texmate cannot assume responsibility for any circuitry described. No circuit patent or software licenses are implied. Texmate reserves the right to change circuitry, operating software, specifications, and prices without notice at any time.

For product details visit www.texmate.com Local Distributor Address



995 Park Center Drive • Vista, CA 92081-8397 Tel: 1-760-598-9899 • USA 1-800-839-6283 • That's 1-800-TEXMATE Fax: 1-760-598-9828 • Email: sales@texmate.com • Web: www.texmate.com Texmate has facilities in Japan, New Zealand, Taiwan, and Thailand. We also have authorized distributors throughout the USA and in 28 other countries.

Copyright © 2004 Texmate Inc. All Rights Reserved.