
WATTS AC

Our customer requires a quality control test for watt/hour rating of electrical appliances. The test is carried out over 5 minutes. A Texmate DI-50E meter with a watt input module is installed. The meter is programmed to totalize the watt/hours when the start button is pressed. The meter totalizes the watts for 5 minutes and the watt/hour rating is held on the display.

When the next appliance is connected, the start button is pressed, the meter is reset to 0 and counts the watts for 5 minutes again. A setpoint is programmed in the deviation mode to indicate PASS/ FAIL. The appliance ON-time is programmable to suit your application.



- · Print quality control receipt.
- RS 232 output to computer for PASS/FAIL analysis for production records.
- For current applications above 5 A, a current transformer is required.

Suggested Ordering Code Options for This Application

Basic Order Codes	Comments	
DI-50E-DR-PS1-IW01-OR12	Two relays to announce "Pass" and "Fail"	
DI-50E-DR-PS1-IW01-OR12-S2	RS-232 to log Data to Printer or PC	