



Typical initial contact



Product Selection Assistance & Custom Solution Consultation




Configuring your custom order



Scheduling manufacturing



Manufacturing base board & custom components




QC Boards


Typical Steps from Ordering to Shipping



TEXMATE Since 1976 MADE IN U.S.A. Smart Measuring Smart Control



Product Development and Improvement




Assembling custom configuration



Packing and Shipping

Calibrating custom measurement range and display reading




Meter Prep and Labeling



24-hour Burn-in Test



Program & Install custom configuration and applications



Final Quality Control